TWO STROKES LIMITED,
CORNWALL ROAD,
HATCH END, MIDDX.

I SAW YOUR ADVERT IN:

TELEPHONE:
01.428.5505
01.428.1985

A SELECTION OF BERKELEY SPARES IN STOCK

BOOKS & PICTURES TO HELP YOU UNDERSTAND YOUR BERKELEY:

BERKELEY OWNERS HANDBOOK reproduced from the original book, including greasing and servicing instructions ... ... £. p. .20

WIRING DIAGRAM. Large picture showing all details of wiring various colours used, etc. ... ... .20

FRONT END DRAWING. Large picture showing all front end, how differential is assembled, front suspension assembly. All parts numbered to help you select your spares ... ... .20

SIBA BOOK ON EXCELSIOR ENGINE, electrics simplified, details on fault finding. ... ... .20

Description		Makers Pt. No.		
Drum Brake, front		M.B.107R		5.25
Master Cylinder Brakes				3.70
Front Stub Axles N/S & O/S.	Service Exchange.	M.B.108/5		5.00
	New			7.50
Oil Ring for the Diff. Housing		M.B.115/1		.08
Mounting for Wishbone		M.B.116M		1.95
Spindle Differential Pinion		M.B.118		.36
Nuts for the Diff. Shaft		M.B.120		.10
Washers Diff. Tab.		M.B.121		.15
Nut for the Diff. Housing		M.B.122		.18
Bushes for the Diff. Shaft		M.B.123		.11
Brake Drum Rear		M.B.127/G		4.25
Grease Nipple for Trunnion Block, angled		M.B.130.N.		.08
Trunnion Block		M.B.130		.98
Trunnion Bolt		M.B.131		.05
Bearing & Housing Steering Col. Gearchange early model		M.B.133		.78
Housing Front Stub Axle		M.B.141		2.10
Bracket Kingpin O/S		M.B.142	New	7.50
			S/Ex	4.50
Bracket Kingpin N/S		M.B.143	New	7.50
			S/Ex	4.50
Front Hub Spacer		M.B.144		.23
Trunnion Pins		M.B.152		.33
Nuts Domed for Front Axle		M.B.156		.38
Spacer Washers for the Front Hub		M.B.156/1		.08
Wishbone Bottom		M.B.157		3.05
Wishbone Top, front suspension		M.B.158		2.13
Block Emulsion Distance Piece for Carb.		M.B.205		.16
Key Woodruff		M.B.242		.09
Drive Chain - 58 links		M.B.329		2.13
Hardy Spicer Joint		M.B.365		4.20
Perspex Headlamp Shield		M.B.358		1.25
Rubber for Shield		M.B.358A		.48
Filler Strip for Rubber		M.B.358B		.13
Nuts for Kingpin		M.B.374		.10
Cable Choke		M.B.379		.63
Silencer to suit M.B.552		M.B.551		4.50
Black Twill Hood & Fittings but minus metal frame		M.B.529		13.25
Exhaust Pipes Siamese		M.B.552		4.50
Cable Handbrake, 5'1" long		M.B.553		1.63
Cable Handbrake, 4'9½" long		M.B.553/1		2.18
Handbrake Ratchet (557) Handbrake Pawl (558)		M.B.557/8		1.00
Cable Handbrake 6'6" long. Umbrella Type.		M.B.1063/1		2.18
Wheel Stud		M.B.1095		.14
Wheel Nut		M.B.1096		.13
Hinge Door		M.B.1105		1.25
Clutch Cable with 5/16" adjuster		M.B.1133		1.68
Engine Mounting Rear		M.B.1168		1.64
Engine Front Mounting		M.B.1169		.74

Description	Makers Pt. No.	£. p.
Bush Steering (Goes in the track rod)	E.2063	.48
Damper T60. Suitable for all wheels.	3082	4.51
Bolts & Nuts for ends of engine tray 7½" long.		.38
Rear Hub Extractor for hire. DEPOSIT £5.	R.H.E.	
Hire charge per week		1.00
Oil Seal for Front Hub and Differential	C.432	.30
Piston Standard c/w Rings & Gudgeon Pin 328cc.	3211	3.80
Piston Rings standard per set for 328cc.	9880V	1.38
Clutch Plates. New. Three in the set.	H.89K. Each Plate	1.11
ditto. S/Ex. ditto.	H.89K. " "	.80
Diff. Shaft Flange	M.B.113	2.50
Track Rods - Supplies of original type track rods have now ceased but we have produced an alternative type with modified outer end. New.	M.B.315/1	5.00
S/Ex.	M.B.315/1	4.00
PLEASE RETURN WORN TRACK RODS WITH ORDER. New.	M.B.315	5.00
S/Ex.	M.B.315	4.00

ELECTRICAL SECTION:

Light Lens White (front of car)	576983	.15
Flasher Lens Front, Amber	576108	.15
Headlamp Bulb		.40
Lens Red for Rear Light	576109	.20
New Control Box for Siba Unit		7.98
Service Exchange Control Box		6.38
Set Contact Breaker Points	31028-20	1.63
Set of Siba Dynastart Brushes	SGT.101	1.18

MISCELLANEOUS SECTION:

Speedo Cable Inner		.63
Speedo Cable Complete		2.00
Brake Shoe (Front - 109) (Rear - 110)	Each Shoe	1.83
Brake Shoe Service Exchange (Front)	Each Shoe	.83
Brake Shoe Service Exchange (Rear)	Each Shoe	.83
Pirelli Tyre. 5.20 x 12		5.13
N/S Side Screens, Aluminium Framed, Sliding Windows	M.B.533 *	5.25
O/S ditto.	M.B.532 *	5.25

* Items M.B.533 and M.B.532 ARE FOR SOFT TOP MODELS ONLY

ADDITIONAL ITEMS:

Replacement For E2050 Susp. Bushes, Engine Tray and Upper Wishbone:

Kit E2050A	Upper	Per Kit	1.26
Kit E2050B	Lower	Per Kit	1.26

Mem53 BEC Archives 1996